## Oil Field Environmental Incident Summary

· ·				, ,,								9	
Incident: 20					ime of No								
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP													
Well Operat					OURCES	OIL 8	& GAS C	OMPA	NY LP				
Well Name: KUMMER 41-30MBH Field Name: BLUE BUTTES  Well File #: 22050												22050	
	<b>dent:</b> 09:3		Well File #: 22050 Facility ID Number:										
Date Incident: 11/11/2015 Time Incident: MCKENZIE							Rng:		•			NE NE	
Location De			-			.00	ruig.		<b>3</b> 00.	00	٠		
Location D	sscripti	1011.											
Submitted By: Lewis Schoenberger					Received By:								
Contact Per	rson:	Lewis	Schoen	berger									
	-1810												
General La	Affected Medium: Well/Facility Soil												
Distance Ne	earest (	Оссир	oied Bui	lding:		0.5	Mile						
Distance Nearest Water Well:				0.5 Mile									
Type of Inc.	i <b>dent</b> :C	Other											
Release Co	ntainec	d in D	ike: Yes	- On Fa	cility Site			Re	eported	l to NF	RC:	No	
	Spille	ed	Units		Recove	red	Units		Fo	llowu	p	Units	
Oil													
Brine	3		Barrels		2.5		Barrels						
Other													
Description	n of Otl	her Re	eleased	Contam	ninant:								
,													
Inspected: Written Report			Received: Clean Up Co					onclu	ncluded:				
Risk Evalu	ation:												
None													

Areal Extent:

Potential Environmental Impacts: None
Action Taken or Planned: The free liquid has been vacuumed up and placed in a tank on site.
Wastes Disposal Location:
Agencies Involved:  Undates

Updates

Date: 11/12/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, 3 barrels of brine were released and contained on the facility site. NDIC retains oversight.